

L Number	Hits	Search Text	DB	Time stamp
1	102	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") same ("aluminum oxide" alumina "al.sub.2o.sus.3" "al.sub.2 o.sub.3") same (molybdenum mo))	USPAT; EPO; JPO; DERWENT	2003/07/31 19:31
2	61	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") same ("aluminum oxide" alumina "al.sub.2o.sus.3" "al.sub.2 o.sub.3") same (molybdenum mo)) ) and lamp	USPAT; EPO; JPO; DERWENT	2003/07/31 19:19
3	5	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") with cermet) and sinter\$ and melt	USPAT; EPO; JPO; DERWENT	2003/07/31 19:32
4	92	("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") and sinter\$ and melt and lamp	USPAT; EPO; JPO; DERWENT	2003/07/31 19:27
5	16	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") with cermet) and sinter\$ and melt\$	USPAT; EPO; JPO; DERWENT	2003/07/31 20:09
6	8934	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") with (ceramic and metal)) and sinter\$ and melt\$	USPAT; EPO; JPO; DERWENT	2003/07/31 20:11
7	53	("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") with (ceramic with metal) and sinter\$ and melt\$	USPAT; EPO; JPO; DERWENT	2003/07/31 20:31
8	2	5,424,609.pn.	USPAT; EPO; JPO; DERWENT	2003/07/31 21:29
9	2	6147453.pn.	USPAT; EPO; JPO; DERWENT	2003/07/31 21:29
-	9	313/623-625.ccls. and cermet and (sinter\$3 same joint)	USPAT; EPO; JPO; DERWENT	2003/07/23 19:49
-	70	313/623-625.ccls. and cermet	USPAT; EPO; JPO; DERWENT	2003/03/18 14:44
-	0	6483230.URPN.	USPAT	2003/03/18 14:09
-	5	("5015916"   "5424609"   "5557169"   "5742124"   "5994839").PN.	USPAT	2003/07/30 14:36
-	0	6465940.URPN.	USPAT	2003/03/18 14:11
-	5	("4354964"   "4412963"   "4694219"   "5271758"   "6066918").PN.	USPAT	2003/03/18 14:58
-	9	5742123.URPN.	USPAT	2003/03/18 14:12
-	6	("4155757"   "4155758"   "4665344"   "4687969"   "4694219"   "4808881").PN.	USPAT	2003/03/18 14:14
-	3	4972119.URPN.	USPAT	2003/03/18 14:15
-	5	4910432.URPN.	USPAT	2003/03/18 14:15
-	4	("3259777"   "4475061"   "4585972"   "4594529").PN.	USPAT	2003/03/18 14:16
-	5	4910432.URPN.	USPAT	2003/03/18 14:16
-	4	4825126.URPN.	USPAT	2003/03/18 14:16
-	9	("2138224"   "2731581"   "3892993"   "4155757"   "4155758"   "4507584"   "4531074"   "4539511"   "4585972").PN.	USPAT	2003/03/18 14:17
-	4	4808882.URPN.	USPAT	2003/03/18 14:19
-	4	4808882.URPN.	USPAT	2003/03/18 14:19
-	18	("3385463"   "3564328"   "4354717"   "4545799"   "4563214"   "4694219"   "4707636"   "4765820"   "4808882"   "4959588"   "5099174"   "5426343"   "5427051"   "5451553"   "5549746"   "5727975"   "5742124"   "6087195").PN.	USPAT	2003/03/18 14:20
-	5	("3363134"   "3564328"   "4501799"   "4539511"   "4665344").PN.	USPAT	2003/03/18 14:22
-	5	("3885184"   "4503356"   "4507584"   "4563214"   "4687969").PN.	USPAT	2003/03/18 14:23
-	1	4800320.URPN.	USPAT	2003/03/18 14:24
-	1	4800320.URPN.	USPAT	2003/03/18 14:29
-	5	("3885184"   "4503356"   "4507584"   "4563214"   "4687969").PN.	USPAT	2003/03/18 14:29
-	11	4687969.URPN.	USPAT	2003/03/18 14:30
-	3	("4503356"   "4507584"   "4563214").PN.	USPAT	2003/03/18 14:33
-	22	5334997.URPN.	USPAT	2003/03/18 14:34
-	15	5075587.URPN.	USPAT	2003/03/18 14:37
-	9	("4150317"   "4156826"   "4481300"   "4687969"   "4689519"   "4766097"   "4777399"   "4827176"   "4949004").PN.	USPAT	2003/03/18 14:38

-	13	(US-6465940-\$ or US-5742123-\$ or US-5532552-\$ or US-4972119-\$ or US-4910432-\$ or US-4825126-\$ or US-4808882-\$ or US-4800320-\$ or US-4687969-\$ or US-5271758-\$ or US-4354964-\$ or US-5075587-\$).did. or (JP-05334997-\$).did.	USPAT; JPO	2003/03/18 14:39
-	11	((US-6465940-\$ or US-5742123-\$ or US-5532552-\$ or US-4972119-\$ or US-4910432-\$ or US-4825126-\$ or US-4808882-\$ or US-4800320-\$ or US-4687969-\$ or US-5271758-\$ or US-4354964-\$ or US-5075587-\$).did. or (JP-05334997-\$).did.) and sinter\$3	USPAT; EPO; JPO; DERWENT	2003/03/18 14:40
-	849	313/623-625.ccls.	USPAT; EPO; JPO; DERWENT	2003/03/18 17:54
-	52	313/623-625.ccls. and cermet and sinter\$3	USPAT; EPO; JPO; DERWENT	2003/03/18 14:44
-	37	313/623-625.ccls. and cermet same sinter\$3	USPAT; EPO; JPO; DERWENT	2003/03/18 14:44
-	10	((US-6465940-\$ or US-5742123-\$ or US-5532552-\$ or US-4972119-\$ or US-4910432-\$ or US-4825126-\$ or US-4808882-\$ or US-4800320-\$ or US-4687969-\$ or US-5271758-\$ or US-4354964-\$ or US-5075587-\$).did. or (JP-05334997-\$).did.) and sinter\$3)	USPAT	2003/03/18 16:40
-	10	((US-6465940-\$ or US-5742123-\$ or US-5532552-\$ or US-4972119-\$ or US-4910432-\$ or US-4825126-\$ or US-4808882-\$ or US-4800320-\$ or US-4687969-\$ or US-5271758-\$ or US-4354964-\$ or US-5075587-\$).did. or (JP-05334997-\$).did.) and sinter\$3) and cermet	USPAT	2003/03/18 17:19
-	1	4,687,989.pn.	USPAT	2003/03/18 16:43
-	1	4687989.pn.	USPAT	2003/03/18 16:45
-	1	4,766,097.pn.	USPAT	2003/03/18 17:09
-	1	6181065.pn.	USPAT	2003/03/18 17:09
-	7	((US-6465940-\$ or US-5742123-\$ or US-5532552-\$ or US-4972119-\$ or US-4910432-\$ or US-4825126-\$ or US-4808882-\$ or US-4800320-\$ or US-4687969-\$ or US-5271758-\$ or US-4354964-\$ or US-5075587-\$).did. or (JP-05334997-\$).did.) and sinter\$3) and cermet and crack\$3	USPAT	2003/03/18 17:19
-	12	("3564328"   "4155758"   "4602956"   "4972119"   "5404078"   "5424608"   "5424609"   "5484315"   "5592049"   "5637960"   "5661367"   "5742124").PN.	USPAT	2003/03/18 17:47
-	9	313/623-625.ccls. and lead-through same cermet	USPAT; EPO; JPO; DERWENT	2003/03/18 17:56
-	32	313/623-625.ccls. and lead same cermet	USPAT; EPO; JPO; DERWENT	2003/03/18 17:56
-	106	"discharge lamp" and ((plug capillary) with length)	USPAT; EPO; JPO; DERWENT	2003/07/17 15:05
-	17	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") same cermet) and (length same (plug capillary)) and discharge and lamp	USPAT; EPO; JPO; DERWENT	2003/07/23 19:04
-	16	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") same cermet) and (length same (plug capillary)) and discharge and lamp) and sinter\$	USPAT; EPO; JPO; DERWENT	2003/07/17 16:17
-	11	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") with sinter\$) same cermet) and (length same (plug capillary)) and discharge and lamp	USPAT; EPO; JPO; DERWENT	2003/07/17 16:19
-	6	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") same cermet) and (length same (plug capillary)) and discharge and lamp) not (((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") with sinter\$) same cermet) and (length same (plug capillary)) and discharge and lamp)	USPAT; EPO; JPO; DERWENT	2003/07/17 16:19
-	0	cermet with ("lead-through" leadthrough "lead through" feedthrough "feed-through" "feed through") same ((("al.sub.2 o.sub.3" alumina "aluminum oxide") and (molybdenum mo)) and "discharge lamp"	USPAT; EPO; JPO; DERWENT	2003/07/17 16:50

-	95	cermet with ("lead-through" leadthrough "lead through" feedthrough "feed-through" "feed through") same ("al.sub.2 o.sub.3" alumina "aluminum oxide") and (molybdenum mo))	USPAT; EPO; JPO; DERWENT	2003/07/17 16:50
-	16	((US-4808882-\$ or US-6528945-\$ or US-6181065-\$ or US-5861714-\$ or US-5532552-\$ or US-5404078-\$ or US-4972119-\$ or US-4825126-\$ or US-4800320-\$ or US-4687969-\$ or US-5271758-\$ or US-4354964-\$ or US-4959588-\$ or US-5075587-\$ or US-5352952-\$ or US-5015913-\$ or US-6404130-\$ or US-4633137-\$).did. or (JP-05334997-\$).did.) and (length mm) and sinter\$	USPAT; EPO; JPO; DERWENT	2003/07/23 16:24
-	16	((US-4808882-\$ or US-6528945-\$ or US-6181065-\$ or US-5861714-\$ or US-5532552-\$ or US-5404078-\$ or US-4972119-\$ or US-4825126-\$ or US-4800320-\$ or US-4687969-\$ or US-5271758-\$ or US-4354964-\$ or US-4959588-\$ or US-5075587-\$ or US-5352952-\$ or US-5015913-\$ or US-6404130-\$ or US-4633137-\$).did. or (JP-05334997-\$).did.) and (length mm) and sinter\$	USPAT; EPO; JPO; DERWENT	2003/07/23 16:24
-	37	("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") with cermet	USPAT; EPO; JPO; DERWENT	2003/07/23 21:44
-	31	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") with cermet) and sinter\$	USPAT; EPO; JPO; DERWENT	2003/07/23 19:06
-	52	313/623-625.ccls. and cermet and sinter\$	USPAT; EPO; JPO; DERWENT	2003/07/23 19:49
-	26	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") same cermet) and thermal and sinter\$	USPAT; EPO; JPO; DERWENT	2003/07/23 19:56
-	19	(US-4808882-\$ or US-6528945-\$ or US-6181065-\$ or US-5861714-\$ or US-5532552-\$ or US-5404078-\$ or US-4972119-\$ or US-4825126-\$ or US-4800320-\$ or US-4687969-\$ or US-5271758-\$ or US-4354964-\$ or US-4959588-\$ or US-5075587-\$ or US-5352952-\$ or US-5015913-\$ or US-6404130-\$ or US-4633137-\$).did. or (JP-05334997-\$).did.	USPAT; JPO	2003/07/23 21:35
-	6	((US-4808882-\$ or US-6528945-\$ or US-6181065-\$ or US-5861714-\$ or US-5532552-\$ or US-5404078-\$ or US-4972119-\$ or US-4825126-\$ or US-4800320-\$ or US-4687969-\$ or US-5271758-\$ or US-4354964-\$ or US-4959588-\$ or US-5075587-\$ or US-5352952-\$ or US-5015913-\$ or US-6404130-\$ or US-4633137-\$).did. or (JP-05334997-\$).did.) and "80%"	USPAT; JPO	2003/07/23 21:35
-	27	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") with cermet) and ("aluminum oxide" alumina "al.sub.2o.sub.3" "al.sub.2 o.sub.3") and (molybdenum mo))	USPAT; EPO; JPO; DERWENT	2003/07/23 21:48
-	1	4354964.PN. and sinter\$	USPAT; EPO; JPO; DERWENT	2003/07/23 21:49
-	27	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") with cermet) and ("aluminum oxide" alumina "al.sub.2o.sub.3" "al.sub.2 o.sub.3") and (molybdenum mo)) and sinter\$	USPAT; EPO; JPO; DERWENT	2003/07/30 16:40
-	19	(US-4959588-\$ or US-5075587-\$ or US-5352952-\$ or US-5015913-\$ or US-5532552-\$ or US-5404078-\$ or US-4972119-\$ or US-4825126-\$ or US-4800320-\$ or US-4687969-\$ or US-4354964-\$ or US-5271758-\$ or US-6404130-\$ or US-4633137-\$ or US-4808882-\$ or US-6528945-\$ or US-6181065-\$ or US-5861714-\$).did. or (JP-05334997-\$).did.	USPAT; JPO	2003/07/29 21:19
-	4	((US-4959588-\$ or US-5075587-\$ or US-5352952-\$ or US-5015913-\$ or US-5532552-\$ or US-5404078-\$ or US-4972119-\$ or US-4825126-\$ or US-4800320-\$ or US-4687969-\$ or US-4354964-\$ or US-5271758-\$ or US-6404130-\$ or US-4633137-\$ or US-4808882-\$ or US-6528945-\$ or US-6181065-\$ or US-5861714-\$).did. or (JP-05334997-\$).did.) and ((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") with cermet) and ("aluminum oxide" alumina "al.sub.2o.sub.3" "al.sub.2 o.sub.3") and (molybdenum mo)) and sinter\$	USPAT; EPO; JPO; DERWENT	2003/07/30 14:36
-	16	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") with cermet) and ("aluminum oxide" alumina "al.sub.2o.sub.3" "al.sub.2 o.sub.3") and (molybdenum mo)) and sinter\$ and \$2%"	USPAT; EPO; JPO; DERWENT	2003/07/30 18:45

-	16	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") with cermet) and ("aluminum oxide" alumina "al.sub.2o.sub.3" "al.sub.2 o.sub.3") and (molybdenum mo)) and sinter\$ and \$2"%	USPAT; EPO; JPO; DERWENT	2003/07/30 16:59
-	16	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") with cermet) and ("aluminum oxide" alumina "al.sub.2o.sub.3" "al.sub.2 o.sub.3") and (molybdenum mo) and sinter\$ and \$2"%	USPAT; EPO; JPO; DERWENT	2003/07/30 16:59
-	16	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") with cermet) and ("aluminum oxide" alumina "al.sub.2o.sub.3" "al.sub.2 o.sub.3") and (molybdenum mo) and \$2"%	USPAT; EPO; JPO; DERWENT	2003/07/30 17:16
-	14	("3848151"   "4851733"   "5075587"   "5352952"   "5404077"   "5404078"   "5424608"   "5424609"   "5446341"   "5532552"   "5552670"   "5592049"   "5637960"   "5742123").PN.	USPAT	2003/07/30 17:02
-	11	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") with cermet) and ("aluminum oxide" alumina "al.sub.2o.sub.3" "al.sub.2 o.sub.3") and (molybdenum mo) not \$2"%	USPAT; EPO; JPO; DERWENT	2003/07/30 17:34
-	11	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") with cermet) and ("aluminum oxide" alumina "al.sub.2o.sub.3" "al.sub.2 o.sub.3") and (molybdenum mo) not \$2"% ) and sinter\$	USPAT; EPO; JPO; DERWENT	2003/07/30 17:27
-	49	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") same (metal with ceramic)) and ("aluminum oxide" alumina "al.sub.2o.sub.3" "al.sub.2 o.sub.3") and (molybdenum mo) not \$2"%	USPAT; EPO; JPO; DERWENT	2003/07/30 17:37
-	15	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") same (metal with ceramic)) and ("aluminum oxide" alumina "al.sub.2o.sub.3" "al.sub.2 o.sub.3") and (molybdenum mo) not \$2"% ) and lamp and sinter\$	USPAT; EPO; JPO; DERWENT	2003/07/30 17:37
-	16	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") with cermet) and ("aluminum oxide" alumina "al.sub.2o.sub.3" "al.sub.2 o.sub.3") and (molybdenum mo)) and sinter\$ and \$2"%	USPAT; EPO; JPO; DERWENT	2003/07/30 18:32
-	2	4,155,758.pn.	USPAT; EPO; JPO; DERWENT	2003/07/30 18:32
-	19	(US-4633137-\$ or US-6404130-\$ or US-5075587-\$ or US-4959588-\$ or US-5271758-\$ or US-4354964-\$ or US-4687969-\$ or US-4800320-\$ or US-4825126-\$ or US-4972119-\$ or US-5404078-\$ or US-5532552-\$ or US-5861714-\$ or US-5352952-\$ or US-5015913-\$ or US-6181065-\$ or US-6528945-\$ or US-4808882-\$).did. or (JP-05334997-\$).did.	USPAT; EPO; JPO; DERWENT	2003/07/30 18:45
-	4	((US-4633137-\$ or US-6404130-\$ or US-5075587-\$ or US-4959588-\$ or US-5271758-\$ or US-4354964-\$ or US-4687969-\$ or US-4800320-\$ or US-4825126-\$ or US-4972119-\$ or US-5404078-\$ or US-5532552-\$ or US-5861714-\$ or US-5352952-\$ or US-5015913-\$ or US-6181065-\$ or US-6528945-\$ or US-4808882-\$).did. or (JP-05334997-\$).did.) and ((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") with cermet) and ("aluminum oxide" alumina "al.sub.2o.sub.3" "al.sub.2 o.sub.3") and (molybdenum mo))	USPAT; EPO; JPO; DERWENT	2003/07/30 18:55
-	102	("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") same ("aluminum oxide" alumina "al.sub.2o.sub.3" "al.sub.2 o.sub.3") same (molybdenum mo)	USPAT; EPO; JPO; DERWENT	2003/07/30 19:39
-	9	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") same ("aluminum oxide" alumina "al.sub.2o.sub.3" "al.sub.2 o.sub.3") same (molybdenum mo)) and "glass melt"	USPAT; EPO; JPO; DERWENT	2003/07/30 19:45
-	8	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") same ("aluminum oxide" alumina "al.sub.2o.sub.3" "al.sub.2 o.sub.3") same (molybdenum mo)) and "glass melt" and direct\$2 near6 sinter\$	USPAT; EPO; JPO; DERWENT	2003/07/30 19:30

-	1	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") same ("aluminum oxide" alumina "al.sub.2o.sus.3" "al.sub.2 o.sub.3") same (molybdenum mo)) and "glass melt") not ((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") same ("aluminum oxide" alumina "al.sub.2o.sus.3" "al.sub.2 o.sub.3") same (molybdenum mo)) and "glass melt" and direct\$2 near6 sinter\$)	USPAT; EPO; JPO; DERWENT	2003/07/30 19:39
-	11	((("feed-through" "feed through" feedthrough leadthrough "lead through" "lead-through") same ("aluminum oxide" alumina "al.sub.2o.sus.3" "al.sub.2 o.sub.3") same (molybdenum mo)) and glass near5 melt	USPAT; EPO; JPO; DERWENT	2003/07/31 19:12
-	2	4602956.pn.	USPAT; EPO; JPO; DERWENT	2003/07/30 19:48